NASA/TM-2002-211381



Predictive Failure of Cylindrical Coatings Using Weibull Analysis

Brian L. Vlcek Georgia Southern University, Statesboro, Georgia

Robert C. Hendricks and Erwin V. Zaretsky Glenn Research Center, Cleveland, Ohio Since its founding, NASA has been dedicated to the advancement of aeronautics and space science. The NASA Scientific and Technical Information (STI) Program Office plays a key part in helping NASA maintain this important role.

The NASA STI Program Office is operated by Langley Research Center, the Lead Center for NASA's scientific and technical information. The NASA STI Program Office provides access to the NASA STI Database, the largest collection of aeronautical and space science STI in the world. The Program Office is also NASA's institutional mechanism for disseminating the results of its research and development activities. These results are published by NASA in the NASA STI Report Series, which includes the following report types:

- TECHNICAL PUBLICATION. Reports of completed research or a major significant phase of research that present the results of NASA programs and include extensive data or theoretical analysis. Includes compilations of significant scientific and technical data and information deemed to be of continuing reference value. NASA's counterpart of peerreviewed formal professional papers but has less stringent limitations on manuscript length and extent of graphic presentations.
- TECHNICAL MEMORANDUM. Scientific and technical findings that are preliminary or of specialized interest, e.g., quick release reports, working papers, and bibliographies that contain minimal annotation. Does not contain extensive analysis.
- CONTRACTOR REPORT. Scientific and technical findings by NASA-sponsored contractors and grantees.

- CONFERENCE PUBLICATION. Collected papers from scientific and technical conferences, symposia, seminars, or other meetings sponsored or cosponsored by NASA.
- SPECIAL PUBLICATION. Scientific, technical, or historical information from NASA programs, projects, and missions, often concerned with subjects having substantial public interest.
- TECHNICAL TRANSLATION. Englishlanguage translations of foreign scientific and technical material pertinent to NASA's mission.

Specialized services that complement the STI Program Office's diverse offerings include creating custom thesauri, building customized data bases, organizing and publishing research results . . . even providing videos.

For more information about the NASA STI Program Office, see the following:

- Access the NASA STI Program Home Page at http://www.sti.nasa.gov
- E-mail your question via the Internet to help@sti.nasa.gov
- Fax your question to the NASA Access Help Desk at 301–621–0134
- Telephone the NASA Access Help Desk at 301–621–0390
- Write to: NASA Access Help Desk NASA Center for AeroSpace Information 7121 Standard Drive Hanover, MD 21076

NASA/TM-2002-211381



Predictive Failure of Cylindrical Coatings Using Weibull Analysis

Brian L. Vlcek Georgia Southern University, Statesboro, Georgia

Robert C. Hendricks and Erwin V. Zaretsky Glenn Research Center, Cleveland, Ohio

Prepared for the Ninth International Symposium on Transport Phenomena and Dynamics of Rotating Machinery sponsored by the Pacific Center of Thermal Fluids Engineering Honolulu, Hawaii, February 10–14, 2002

National Aeronautics and Space Administration

Glenn Research Center

This report is a formal draft or working paper, intended to solicit comments and ideas from a technical peer group.

Available from

NASA Center for Aerospace Information 7121 Standard Drive Hanover, MD 21076 National Technical Information Service 5285 Port Royal Road Springfield, VA 22100

Predictive Failure of Cylindrical Coatings Using Weibull Analysis

Brian L. Vlcek Georgia Southern University Statesboro, Georgia 30460–8045

Robert C. Hendricks and Erwin V. Zaretsky National Aeronautics and Space Administration Glenn Research Center Cleveland, Ohio 44135

Summary

Rotating, coated wiping rollers used in a high-speed printing application failed primarily from fatigue. Two coating materials were evaluated: a hard, cross-linked, plasticized polyvinyl chloride (PVC) and a softer, plasticized PVC. A total of 447 tests was conducted with these coatings in a production facility. The data were evaluated using Weibull analysis. The softer coating produced more than twice the life of the harder cross-linked coating and reduced the wiper replacement rate by two-thirds, resulting in minimum production interruption.

Introduction

Intaglio printing is used in high-quality applications where a desired texture is imparted to the finished print product along with the ink. In this printing process, ink is applied to the entire surface of the printing plate, although ink is ultimately desired only in the engraved valleys of the plate. The excess ink on the flat plateaus between the engraved valleys (known in the trade as the "lands") must be removed before it is transferred to the printed product. The paper is then squeezed against the plate with such force that ink is transferred from the capillary-like engraved lines, and the surface of the paper is textured and/or deformed.

A coated cylinder is used as a wiping roller to remove the excess ink from the printing plates. The wiper rotates and oscillates from side to side as excess ink is removed from the printing plate surface before impressions are made. On press, the wiping roller sits in a tank of caustic solution where ink is removed physically, by brushes and blades located in the tank, and chemically, from the wiper surface.

In an application of high-speed Intaglio printing, the surface coating of rotating cylindrical wiping rollers fails because of fatigue and/or misuse. Microscopic and visual inspections of failed wiper surfaces show that the primary mode of failure is fatigue. Fields of cracks 10 to $30~\mu m$ wide and 100 to $300~\mu m$ long form on the surface of failed coatings. Figure 1 is a micrograph of a failed wiper coating surface shown at a magnification of 100. Excess ink that has become entrapped in the fatigue cracks is transferred to the printing plates, imprinting the fatigue crack images on the finished product. The failure criterion is artistically driven and is based upon the appearance of the printed product. Thus, wipers are removed not at the first appearance of fatigue cracks on the surface but at the first visual appearance of a crack image transferred to the printed product.

Based upon the fatigue criterion, a test was conducted to determine the endurance of the roller coatings. The standard coating used was manufactured in-house by the user and was a hard, cross-linked, plasticized polyvinyl chloride (PVC) thermoset. The candidate replacement coating was a softer plasticized PVC. The objectives of the research were to (a) determine the fatigue life of each of the coatings, (b) determine the rate of coating replacement due to failure, and (c) minimize the impact of early failures.




Figure 1.—Fatigue cracks on surface of failed wiper roller coating.

Statistical Method

Weibull Method

Waloddi Weibull (1939a,b, 1951) developed a method for statistically evaluating the fracture strength of materials based upon small population sizes. He stated that the dispersion in material strength for a group of homogeneous test specimens can be expressed by

$$\ln \ln \frac{1}{S} = e \ln \left[\frac{X}{X_{\beta}} \right] \tag{1}$$

where S is the probability of survival as a fraction (0 < S < 1), X is the stress or strength $(N/m^2 \text{ or psi})$, and X_{β} is the characteristic stress or strength $(N/m^2 \text{ or psi})$. By plotting the ordinate scale as $\ln \ln(1/S)$ and the abscissa scale as $\ln X$, a cumulative distribution will plot as a straight line, which is called a "Weibull plot." Usually, the ordinate is graduated in statistical percent of specimens failed. Figure 2 is a generic Weibull plot with some of the values of interest indicated.

The Weibull plot can be used to evaluate phenomena that result in a statistical distribution. The tangent of the resulting plot, called the Weibull slope and designated by *e* or *m*, defines the statistical distribution. Weibull slopes of 1, 2, and 3.57 represent exponential, Raleigh, and Gaussian (normal) distributions, respectively. Lundberg and Palmgren (1947) were the first to use Weibull analysis to predict the lives of rolling-element bearings.

The statistical method for plotting and evaluating data using Weibull analysis was developed by Johnson (1951, 1964). It is assumed that a straight line is representative of the data, even though in many cases the data loci are not linear. Using the method of least squares, a straight line is drawn through an array of points on each plot. From this straight line, two significant lives are obtained for comparison: these are the lives at which 10 and 50 percent of the specimens have failed and are designated L_{10} and L_{50} , respectively. The failure index given with each plot indicates the number of failed specimens of those tested. The confidence number is a comparison of the repeatability of the test results. It is dependent upon the number of failures in each group of specimens, the ratio of the lives being compared, and the Weibull slope of each group. A confidence number of 90 percent indicates that 90 out of 100 times the qualitative results would be the same if the tests were to be repeated.




Figure 2.—Sketch of Weibull plot where (Weibull) slope or tangent of line is m, S_{β} is probability of survival of 36.8 percent at which $X = X_{\beta}$ or $X/X_{\beta} = 1$ (from Melis, Zaretsky, and August, 1999).

From the Weibull plot, the values of e and X_{β} are determined. With these values known, it is possible to determine the failure rate for any time increment from equation (1).

Premature Failures

Wiper coatings were known to fail prematurely in production as a result of accidents such as blade cuts rather than from fatigue. In an attempt to isolate the fatigue characteristics of both wiper materials being evaluated, early failures were intentionally converted to suspensions (removed from press for reasons other than for a fatigue-failed surface). A life was selected at the point below which all failures were converted to suspensions. This life was determined after finding a natural break in the data set and/or after observing distinct differing regions in the Weibull plots. The probability of failure was determined for this new data set and plotted on Weibull paper as a function of life. Weibull slope and the L_{10} and the L_{50} lives were again determined from the plot.

Specimen and Procedure

Materials

Two wiper coatings were evaluated in production. The P-series coating was a hard, cross-linked, plasticized PVC thermoset. High-temperature curing and thermal-driven crosslinking resulted in a Shore D 48 hardness. For the A-series coating, high-temperature curing resulted in a plasticized PVC surface with a Shore D 28 hardness. Both coating materials were produced in-house by the user and were utilized on the press to produce the backside of a printed surface.

Test Method

The test method was driven by production printing practices. The two wiper coatings (P and A) were evaluated on six backpresses as part of normal production usage (a backpress is a press that prints on the backside of the product). The wiper coatings were inspected upon removal of the wipers from the presses. To refurbish the cylindrical wipers, the coatings were removed and/or stripped, and the wipers were recoated for future use. The wiper cores that could not be refurbished were repaired or discarded.

Three hundred and forty-three A-series coated wipers were evaluated over a 9-month period. Of the 343 wiper surfaces, 265 were reported as failures and 78 as suspensions. Of the 104 P-series coated wipers tested on the same 6 backpresses during the same time period, 85 failed and 19 were suspended.

The analysis of the data involves a single backpress and a group of six backpresses and is discussed in the following section. The impact of premature failures is also investigated by intentionally suspending failures below a certain threshold and determining the effect of material and failure distribution on replacement rate.

Results and Discussion

Rotating, cylindrical, coated wiping rollers used in Intaglio printing failed primarily because of fatigue or misuse. Two coating materials were evaluated in a production facility that had six printing presses dedicated to printing the backside of a product. The standard coating used was a hard, cross-linked, plasticized PVC thermoset designated as P-series. The candidate replacement coating was a plasticized PVC designated as A-series. A total of 104 P-series coatings and 343 A-series coatings was tested over 9 months and was evaluated during printing production.

A Weibull analysis was performed on the results to determine which of the wiper coatings was significantly better. The Weibull slope L_{10} and L_{50} lives were determined for each material. Confidence levels comparing the two materials on all six backpresses were determined.

Data From a Single Backpress

These data are from only one backpress and the two materials (A and P). Of the 24 P-series coatings, 21 were failures and 3 were suspensions. Of the 56 A-series coatings, 42 were tested to failure and 14 were suspended. The results are shown in figure 3 and are summarized in table I. Of the two materials, the A-series coating is the longer lived by a factor of 1.5 at the L_{10} life. The method of Johnson (1964) was used to obtain a confidence level of 77 percent.




Figure 3.—Weibull plot of A-series and P-series wiper coating data from single backpress. Failure index: A-series, 42/56; P-series, 21/24.

TABLE I.—SUMMARY OF WEIBULL RESULTS FOR P-SERIES AND A-SERIES COATING DATA FROM SINGLE BACKPRESS

	Wiper coating material on single backpress	
	P-series	A-series
Life, ^a stress cycles		
L_{10}	30 169	46 595
L_{50}	86 902	199 145
Average life, ^b stress cycles	81 460	194 294
Weibull slope, e	1.78	1.30
Failure index ^c	21/24	42/56
Confidence number, d percent	77	77

^aLives at which 10 and 50 percent of specimens failed.

Data From Six Backpresses

The data from the six backpresses were combined for each of the two coatings (P-series and A-Series) tested. Of the 104 P-series coated wipers tested, 85 failed and 19 were suspended. Of the 343 A-series coatings, 265 failed and 78 were suspended. The results of these tests are shown in figure 4 and are summarized in table II. The L_{10} life of the A-series coating was approximately 2.3 times that of the P-series. The confidence number for these data was 99 percent.




Figure 4.—Weibull plot of A-series and P-series wiper coating data combined from six backpresses. Failure index: A-series, 265/343; P-series, 85/104.

TABLE II.—SUMMARY OF WEIBULL RESULTS FOR P-SERIES AND A-SERIES COATING DATA COMBINED FROM SIX BACKPRESSES

	Wiper coating material on all backpresses	
Life, a stress cycles	P-series	A-series
L_{10}	25 402	58 774
L_{50}	102 886	194 179
Average life, b stress cycles	95 168	186 206
Weibull slope, e	1.35	1.58
Failure index ^c	85/104	265/343
Confidence number, d percent	99	99

^aLives at which 10 and 50 percent of specimens failed.

^bTotal life of all specimens (including suspensions) divided by number of specimens (including suspensions).

^cNumber (numerator) of failures out of total tested (denominator).

^dPercent of time qualitative test results will be same if test is repeated.

^bTotal life of all specimens (including suspensions) divided by number of specimens (including suspensions).

^cNumber (numerator) of failures out of total tested (denominator). ^dPercent of time qualitative test results will be same if test is

repeated.

Backpress Data Evaluation With Enforced Suspensions

As was experienced in production, early failures were exhibited in these data. To evaluate the effect of these early failures on the life of each coating population, failures below a clear, natural break in the data set were suspended. These early failures were assumed to result from mishandling by the operator and not from fatigue failure. For the P-series data on all backpresses, all failures below 50 000 impressions were manually converted to suspensions. The six longest lives were also suspended, resulting in a comparatively straight line (fig. 5). The A-series data set was suspended for values less than 90 000 impressions. The Weibull slope and reliability for these suspended results are provided in table III. The ratio of the L_{10} lives was 1.6. The confidence number was 96 percent. Eliminating the early failures from the analysis did not have a significant effect on the relative life of the coatings, which suggested that early failures were coating related.




Figure 5.—Weibull plot of A-series and P-series wiper coating data combined from six backpresses with suspensions. Failure index: A-series, 204/343; P-series, 64/104.

TABLE III.—SUMMARY OF WEIBULL RESULTS FOR P-SERIES AND A-SERIES COATING COMBINED DATA [Includes enforced suspensions from six backpresses.]

	Wiper coating material on all	
	backpresses	
Life, a stress cycles	P-series	A-series
L_{10}	69 360	112 757
L_{50}	113 390	247 548
Average life, stress cycles ^b	95 168	186 206
Weibull slope, e	3.83	2.40
Failure index ^c	64/104	204/343
Confidence number, percent	96	96

^aLives at which 10 and 50 percent of specimens failed.

^bTotal life of all specimens (including suspensions) divided by number of specimens (including suspensions).

^cNumber (numerator) of failures out of total tested (denominator).

^dPercent of time qualitative test results will be same if test is repeated.

Wiper Replacement Protocol

Herein, assume that individual presses make 8000 impressions an hour. Thus, an individual coating receives 8000 stress cycles per hour or 64 000 stress cycles in an 8-hr shift. Using equation (1) and the data from figure 4 and table II for the P-series coating, 31 percent of the coatings would fail before the 8-hr shift were completed. If the remaining wipers were not replaced before the next 8-hr shift, an additional 30 percent of the original coatings would fail and need to be replaced.

For the A-series coating data from figure 4 and table II, the replacement rate for an 8-hr shift was 11 percent or one-third that of the P-series coating. Over two shifts, or 16 hr, 30 percent of the total coatings would be replaced. The replacement rate on the second 8-hr shift would be twice that of the first 8-hr shift. It can be reasonably concluded that by replacing the P-series coating with the A-series coating and replacing all wipers after each 8-hr shift, the failure rate of the wipers during an 8-hr shift could be reduced by approximately two-thirds. A cost-benefit analysis would be required before making a business decision based on these findings.

Summary of Results

Rotating, cylindrical, coated wiping rollers used in Intaglio printing failed primarily by fatigue. Two coating materials were evaluated in a production facility that had six printing presses dedicated to printing the backside of a product. In a 9-month period, over 400 wiper coatings were evaluated in printing production. The P-series coating was a hard, cross-linked, plasticized polyvinyl chloride (PVC) thermoset. The candidate replacement coating was a softer, plasticized PVC designated as A-series. A total of 104 P-series coatings and 343 A-series coatings was tested. The following results were obtained:

- 1. The A-series coating had over twice the life of the P-series coating and a confidence level of 99 percent. During an 8-hr shift, the wiper replacement rate was reduced by approximately two-thirds.
- 2. A minimum failure rate of 11 percent was attained by replacing all A-series coated wipers after each 8-hr shift, resulting in minimum production interruption.
- 3. The suspension of early failures in the analysis did not significantly alter the ratio of L_{10} lives (life at which 10 percent of the specimens have failed). This result suggested that early failures were coating and not operator related.

References

- Johnson, L.G. (1951): The Median Ranks of Sample Values in Their Population with an Application to Certain Fatigue Studies. Industrial Mathematics, vol. 2, pp. 1–9.
- Johnson, L.G. (1964): The Statistical Treatment of Fatigue Experiments. Elsevier Publishing Co., Amsterdam.
- Lundberg, G.; and Palmgren, A. (1947): Dynamic Capacity of Rolling Bearings. Acta Polytechnica, Mechanical Engineering Series, vol. 1, no. 3, Stockholm.
- Melis, M.E.; Zaretsky, E.V.; and August, R. (1999): Probabilistic Analysis of Aircraft Gas Turbine Disk Life and Reliability. AIAA Trans., J. Propulsion and Power, vol. 15, no. 5, pp. 658–666.
- Weibull, W. (1939a): A Statistical Theory of the Strength of Materials. Ingeniors Vetanskaps Akademien-Handlinger, no. 151.
- Weibull, W. (1939b): The Phenomenon of Rupture in Solids. Ingeniors Vetanskaps Akademien-Handlinger, no. 153.
- Weibull, W. (1951): A Statistical Distribution Function of Wide Applicability. Trans. ASME, J. Applied Mechanics, vol. 18, no. 3, pp. 293–297.

REPORT DOCUMENTATION PAGE			Form Approved OMB No. 0704-0188
gathering and maintaining the data needed,	and completing and reviewing the collection	n of information. Send comments rega	eviewing instructions, searching existing data sources, earding this burden estimate or any other aspect of this Information Operations and Reports, 1215 Jefferson Project (0704-0188), Washington, DC 20503.
1. AGENCY USE ONLY (Leave blan	•		ND DATES COVERED
	July 2002	Γ	echnical Memorandum
4. TITLE AND SUBTITLE			5. FUNDING NUMBERS
Predictive Failure of Cylin	ndrical Coatings Using Weibul	ll Analysis	
6. AUTHOR(S)			WU-274-00-SR-00
Brian L. Vlcek, Robert C.	Hendricks, and Erwin V. Zare	etsky	
7. PERFORMING ORGANIZATION NAME(S) AND ADDRESS(ES) 8.			8. PERFORMING ORGANIZATION REPORT NUMBER
National Aeronautics and	Space Administration		TIET OTT NOMBETT
John H. Glenn Research Center at Lewis Field Cleveland, Ohio 44135–3191			E-13128-1
9. SPONSORING/MONITORING AG	ENCY NAME(S) AND ADDRESS(E	ES)	10. SPONSORING/MONITORING AGENCY REPORT NUMBER
National Agrangutics and	Space Administration		AGENCT REPORT NOWIBER
National Aeronautics and Space Administration Washington, DC 20546–0001			NASA TM—2002-211381
11. SUPPLEMENTARY NOTES			1
sored by the Pacific Cente Georgia Southern Univers	r of Thermal Fluids Engineeri	ing, Honolulu, Hawaii, Feb 0–8045; Robert C. Hendric	namics of Rotating Machinery spon- ruary 10–14, 2002. Brian L. Vlcek, ks and Erwin V. Zaretsky, NASA Glenn 216–433–3241.
12a. DISTRIBUTION/AVAILABILITY	STATEMENT		12b. DISTRIBUTION CODE
Unclassified - Unlimited Subject Category: 37	Dis	stribution: Nonstandard	
Available electronically at http			
This publication is available from 13. ABSTRACT (Maximum 200 wor	om the NASA Center for AeroSpac	ce Information, 301–621–0390.	
Rotating, coated wiping romaterials were evaluated: of 447 tests was conducted. The softer coating produce	ollers used in a high-speed prina hard, cross-linked, plasticized with these coatings in a production.	ed polyvinyl chloride (PVC duction facility. The data w the harder cross-linked coa	marily from fatigue. Two coating C) and a softer, plasticized PVC. A total ere evaluated using Weibull analysis. ating and reduced the wiper replacement
14. SUBJECT TERMS			15. NUMBER OF PAGES
Weibull; Fatigue; Coatings; Printing		13 16. PRICE CODE	
, 6,			
17. SECURITY CLASSIFICATION OF REPORT	18. SECURITY CLASSIFICATIO OF THIS PAGE	N 19. SECURITY CLASSIFIC OF ABSTRACT	ATION 20. LIMITATION OF ABSTRACT
Unclassified	Unclassified	Unclassified	

Form Approved